January 11-13, 2011 San Diego, CA

"OEM BAD MARKS -U.S. MARINE CORPS EXPERIENCE"

Blount Island Command



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

- A significant number of Manufacturer IUID marking defects are being discovered. These include:
 - 1. Data Matrix is unreadable by any scanner
 - 2. Data Matrix does not comply with ECC 200 symbol (ISO/IEC 16022)
 - 3. Data Matrix does not contain proper syntax (ISO/IEC 15434) Example: Header, Record Separator, End of Transmission
 - 4. Data Matrix does not contain proper semantics (ISO/IEC 15418 or ATA CSDD). Example: Data Identifiers, Application Identifiers
 - 5. Data Matrix contains incorrect item data
 - 6. Item is marked but not registered or Item is registered but not marked
 - 7. Item is registered with incorrect data



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

• **TAM:** A2043, A2044

• Nomenclature: PRC-148 Urban (V1) & (V2)

• **NSN:** 5820-01-487-0973, 5820-01-487-0972

Manufacturer: Thales Corporations, Inc.







- Data matrix is damaged and cannot be read
- Some part number's in the UII do not match the item's part number
- Some Ulls do not contain the proper syntax
- Some UIIs have a serial number in the UII that does not match the item serial number
- Some IIIIs are not in the registry.



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

• **TAM:** D0017

• **Nomenclature:** M1102 MCC Trailer

• **NSN:** 2330-01-543-5794

Manufacturer: Shutt Industries, Inc.







- Data Matrix is unreadable by any scanner: Poor quality dot peen mark from manufacturer
- Some Ulls do not match registry data
- Some Ulls are not registered at all



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

• **TAM:** C7033

Nomenclature: SHOP EQUIP CONTACT MAINT

VEHICLE

• **NSN**: 4940-01-333-8471

Manufacturer: US Army Armament Research







Defects Found

 Data Matrix does not contain proper syntax (i.e., header). IUID mark contains item's literal data.



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

• **TAM:** D0215

Nomenclature: MK970 SemiTrl Tanker

• **NSN:** 2330-01-537-8217

Manufacturer: Heil Trailer International







- Data Matrix does not contain proper semantics Unknown Data Identifier found "VIN"
- Some marks contained syntax header with no item data
- Some items were registered using VIN method and did not match IUID mark



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

• **EC**: 512235

Nomenclature: TRAILER ECU GEN

• **NSN:** 8340-01-533-1697

Manufacturer: HDT Expeditionary Systems, Inc.





Defect

 Data matrix does not contain proper syntax and contains literal item data



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA


• **TAM**: D0195

Nomenclature: FLATRACK, PALLETIZED

• **NSN:** 3990-01-537-1045

Manufacturer: Summa Technology, Inc.







Defects Found

 Data matrix does not meet ISO format standard. Invalid ISO 15434 Header - The first 3 characters found are "CAG"



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

TAM: B0640 EC: 511024

Nomenclature: FLOODLIGHT SET, ELECTRIC

6230-01-530-8890 / 6330LLLC10766 **NSN:**

Magnum Products Manufacturer:







- IUID mark does not contain proper syntax (i.e., header)
- Manufacturer used UII Construct 2 for creating the data matrix however registered the item using UII Construct 1





IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

• **EC**: 07002

Nomenclature: TRICON

• **NSN:** 8145LLLCC2971

Manufacturer: Charleston Marine Containers, Inc.







- IUID marks do not contain the proper syntax.
- IUID marks contain literal data identifiers
- Manufacturer registered items with UII that did not match data



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

• **TAM:** D0201

Nomenclature: MULTI-FUEL MOTORCYCLE

• **NSN:** 2340-01-530-9371

• Manufacturer: Hayes Diversified Technologies, Inc.







Defects Found

Items marked correctly but not registered



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

• **TAM:** A0273 / A0097

Nomenclature: RADIO SET (20w) / (50w)

• **NSN:** 5820-01-557-8450 / 5820-01-565-

9999

Manufacturary Larris, Inc.





- A0273 contained "Parent" IUID labels to be applied on the record jacket. A0097 did not come with "Parent" labels
- Some radio sets have the parent IUID registered and others do not
- Some subcomponent UIIs have not been registered

IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

BICmd Summary OEM Errors

| | Summary: OEM Marked Items Processed | | | |
|-----------------------|-------------------------------------|---------------------------------|-------------------|--|
| | OEM Mark Scanned | IUID Registere d Verified | Marking Errors | |
| Marine Corps Items | 2,434 | 1,702 | 732 | |
| Navy Items | 24 | 9 | 15 | |
| Totals | 2,458 | 1,711 | 747 | |



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

Manufacturers With High Incidence of IUID Marking Defects

| Manufadurer | Itemid | NSN | Nomendature |
|------------------------------------|--------|------------------|-----------------------------------|
| CHARLESTON MARINE CONTAINERS. INC. | 07002 | 8145111.002971 | TRICON |
| FMW COMPOSITE SYSTEMS INC. | B0036 | 4930015339826 | TANK AND PUMP UNIT |
| | B0037 | 4930015339830 | TANK AND PUMP UNIT |
| HDT EXPEDITIONARY SYSTEMS INC. | 512235 | 8340015331697 | TRAILER ECU GEN |
| HEILTRAILER INTERNATIONAL | D0215 | 2330015378217 | SEMI-TRAILER.REFUELER |
| KIPPER TOOL COMPANY | B0032 | 5180015508112 | PIONEER KIT |
| LEX PRODUCTS . INC. | B0032 | 6110015321776 | PANEL POWER DISTRIBUTION |
| MACNI IM DDOD ICTC | 511024 | 6230015308890 | FLOODLIGHT SET. ELECTRIC |
| MAGNUM PRODUCTS | B0640 | 6230015308890 | FLOODLIGHT SET. ELECTRIC |
| SCHUTT INDUSTRIES, INC. | C7905 | 4940015504312 | SHOP EOUIPMENT.GENERAL PURPOSE |
| | D0017 | 2330015435794 | LIGHT TACTICAL TRAILER, MARINE CO |
| SUMMA TECHNOLOGY INC. | D0195 | 3990015371045 | FLATRACK.PALLETIZED LOADING |
| LIADDIC INC | A0273 | 5820-01-557-8450 | RADIO SET (20w) |
| HARRIS, INC. | A0097 | 5820-01-565-9999 | RADIO SET (50w) |
| THALES CORPORATION INC | A2043 | 5820-01-487-0973 | PRC-148 Urban (V1) |
| THALES CORPORATION, Inc. | A2044 | 5820-01-487-0972 | PRC-148 Urban (V2) |
| MECHANICAL FOUIPMENT COMPANY | B1570 | 4930011825028 | PUMP ASSEMBLY EXPEDIENT REFUEL |
| CRANE PUMPS & SYSTEMS INC. | B1581 | 4320013181853 | MODULE.WATER PUMP |



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

Manufacturer's With 80% of Defects At Blount Island Command

| Manufacturer | ItemID | NSN | Nomendature | % |
|--|--------|---------------|-----------------------------------|--------|
| W.S. DARLEY & CO. | B0676 | 4320011101993 | FORWARD WATER POINT SET | 0.9% |
| WESTWOOD CORPORATION | 512461 | 6115014620291 | GENERATOR SET. DIESEL ENGINE | 1.1% |
| HARRIS CORPORATION | A2068 | 5820014622484 | RADIO SET | 1.1% |
| IOHN DEERE SHARED SERVICES INC. | B0060 | 2320015585671 | TRACTOR.MEDIUM CRAWLER | 1.1% |
| W.S. DARLEY & CO. | B1135 | 4930001881701 | HELICOPTER FUEL SERV SYS | 1.1% |
| MANITEX LOAD KINGINC. | B2565 | 2330015470272 | TRAILER,FLAT BED | 1.1% |
| BAE SYSTEMS LAND & ARMAMENTS L.P. | E0071 | 2540015464267 | ARMOR SET. SUPPLEMENTAL SMALL AR | 4 1.7% |
| SHUTT INDUSTRIES. INC | C7905 | 4940015504312 | COMMON 22, SHOP SET | 1.9% |
| HEILTRAILER INTERNATIONAL | D0215 | 2330015378217 | SEMI-TRAILER, REFUELER | 2.1% |
| HAYES DIVERSIFIED TECHNOLOGIES INC | D0201 | 2340015309371 | MULTI-FUEL MOTORCYCLE | 2.7% |
| SEA BOX INC. | B0075 | 4130015657655 | SMALL FIELD REFRIGERATION SYSTEM | 3.3% |
| HARRIS CORPORATION | A2042 | 5820014923628 | RADIO.HIGH FREOUENCY MANPACK | 3.6% |
| MAGNUM PRODUCTS LLC | B0640 | 6230015308890 | FLOODLIGHT SET.ELECTRIC | 4.3% |
| W.S. DARLEY & CO. DBA OHLER PUMPS DIV OHLER PUMP | B1580 | 4930012404579 | FUEL PUMP MODULE AY | 4.3% |
| MECHANICAL EOUIPMENT COMPANY | B1570 | 4930011825028 | PUMP ASSY. EXP REFUE | 4.8% |
| CRANE PUMPS & SYSTEMS INC. | B1581 | 4320013181853 | MODULE.WATER PUMP | 5.1% |
| HDT EP INC. | B0014 | 4120015262397 | AIR CONDITIONER.3 TON | 8.6% |
| MECHANICAL EOUIPMENT COMPANY INC. | B1620 | 4320014764795 | PUMP UNIT SET | 10.2% |
| SCHUTT INDUSTRIES. INC. | D0017 | 2330015435794 | LIGHT TACTICAL TRAILER, MARINE CO | 21.1% |
| | | | | 79.9% |

IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

Summary

- Manufacturer IUID marking errors are being identified at an alarming rate
- Manufacturer's must be held accountable for ensuring that their item's IUID mark is valid and registered

DOD Recommended COA

 Enforce DoD policy which mandates that new item acceptance testing <u>includes</u> <u>IUID validation</u>



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

POCs

703-582-1636

904-714-6225

703-786-3638



IUID Implementation: Making Every Dollar Count

January 11-13, 2011 San Diego, CA

Questions

